



Ronco Safety products recycling flow chart


Flexible reusable PPE
Shredding → Demetallization & Eddy Current → Air Washing → Densification & Extrusion → Mixing → Thermokinetic molding



Polypropylene PPE
Shredding → Demetallization & Eddy Current → Air Washing → Densification & Extrusion → Pelletization



Disposable Gloves
Shredding → Air Washing → Devulcanization → Formulation and compounding → Molding



Rigid reusable PPE
Shredding → Demetallization & Eddy Current → Air Washing → NIR separation → Extrusion → Pelletization

